Professional Audio Products Technical Bulletin 89–016

Sony Technology and Engineering Operation Training and Publications 677 River Oaks Pkwy. San Jose, California 95134

Date: March, 1989

Subject: MANUAL CORRECTION-PINCH ROLLER

SPECIFICATION

Model: APR-5000

Serial No: 10,001 AND HIGHER

DESCRIPTION

Correct the APR-5000 Maintenance Manual as shown in Figure 1.




Figure 1