

**Analog**Date: **November, 1990**Model: **APR-5003V**Serial No: **11,301-11,330**Subject: **HOURL METER—EXCESSIVE TIME  
INDICATION****DESCRIPTION**

The hour meter of some units may indicate excessive time not relative to real time operation. If this occurs, inspect R57 on the CSL board to confirm that its value is 270k $\Omega$ . If not, replace R57 with a 270k $\Omega$  resistor.

**PARTS REQUIRED**

Part No.	Description	Qty.
1-247-889-00	Res, 270k $\Omega$ , Carbon, 1/6W, 5%	1